HA-1493

Chandler House 133 Thomas Bel Air Private

This is the best kept house in a row of two bay shotgun houses. It shows how attractive these modest homes can be, especially with roses climbing up a porch trellis.

## INVENTORY FORM FOR STATE HISTORIC SITES SURVEY

1 NAME				
HISTORIC				
AND/OR COMMON				
Chandler Ho				<del></del>
2 LOCATION				
STREET & NUMBER			<b>-</b> .	
133 Thomas Street		1st CONGRESSIONAL DISTRI	ICT.	
CITY, TOWN		VICINITY OF	CONGRESSIONAL DIGIN	
STATE COUNTY				
Maryland			Harford	
3 CLASSIFIC	ATION			
CATEGORY	OWNERSHIP	STATUS	PRES	ENTUSE
DISTRICT	PUBLIC	X OCCUPIED	AGRICULTURE	MUSEUM
X BUILDING(S)	X_PRIVATE	UNOCCUPIED	COMMERCIAL	PARK X PRIVATE RESIDENCE
STRUCTURE	_вотн	WORK IN PROGRESS	EDUCATIONAL	
SITE	PUBLIC ACQUISITION	ACCESSIBLE X YES: RESTRICTED	ENTERTAINMENT GOVERNMENT	RELIGIOUS SCIENTIFIC
OBJECT	IN PROCESSBEING CONSIDERED	YES: UNRESTRICTED	INDUSTRIAL	TRANSPORTATION
	_BEING CONSIDERED	NO	MILITARY	_OTHER:
Mrs. Mazie STREET & NUMBER 133 Thomas			Telephone #: 83	
CITY, TOWN				ip code
Bel Air		VICINITY OF	Maryland	21014
5 LOCATION	NOF LEGAL DESCR	IPTION	Liber #: 288	
COURTHOUSE			Folio #: 315	
REGISTRY OF DEEDS,	ETC. Harford County	Courthouse		
STREET & NUMBER	Main Street		<del></del> -	
CITY, TOWN			STATE	
	Bel Air		Maryland	
6 REPRESEN	<b>ITATION IN EXIST</b>	ING SURVEYS		
TITLE				
DATE		FEDERAL	STATECOUNTYLOCAI	L
DEPOSITORY FOR				
SURVEY RECORDS				
CITY, TOWN			STATE	
				<del>_</del>

NA-1493

CONDITION

CHECK ONE

CHECK ONE

X\_EXCELLENT

\_\_DETERIORATED

\_UNEXPOSED

\_\_UNALTERED

X\_ORIGINAL SITE

\_GOOD

\_\_RUINS

X\_ALTERED

\_\_\_MOVED DATE\_\_\_\_\_

DESCRIBE THE PRESENT AND ORIGINAL (IF KNOWN) PHYSICAL APPEARANCE

This small, two-bay, two-story shot-gun house is at 133 Thomas Street in the Town of Bel Air, Harford County, Maryland. Its shiplap siding shines a sparkling white showing that this is an owner-occupied house. The windows are 6/6 double-hung sash set in plain, thin surrounds. The original half-glass door is topped by a two pane transom. The shed porch with a plain balustrade is carried on chamfered posts. The center chimney has a corbelled cap. The shed addition in back has been extended one bay to the west. This extension is covered in asphalt siding and has a single 4 pane casement in the front (north) elevation.

Red roses climb a trellis on the east side of the front porch, reminding us how attractive these humble homes can be when well kept.

## 8 SIGNIFICANCE

PERIOD	AREAS OF SIGNIFICANCE CHECK AND JUSTIFY BELOW			
PREHISTORIC	_ARCHEOLOGY-PREHISTORIC	COMMUNITY PLANNING	LANDSCAPE ARCHITECTURE	RELIGION
1400-1499	_ARCHEOLOGY-HISTORIC	CONSERVATION	_LAW	_SCIENCE
1500-1599	AGRICULTURE	ECONOMICS	LITERATURE	SCULPTURE
1600-1699	X_ARCHITECTURE	EDUCATION	MILITARY	_SOCIAL/HUMANITARIAN
_1700-1799	ART	ENGINEERING	MUSIC	THEATER
X_1800-1899	COMMERCE	_EXPLORATION/SETTLEMENT	PHILOSOPHY	TRANSPORTATION
<u>X_1900</u> .	COMMUNICATIONS	_INDUSTRY _INVENTION	POLITICS/GOVERNMENT	_OTHER (SPECIFY)
SPECIFIC DAT	TES 1885	BUILDER/ARCH	HITECT John F. Lir	ngan

STATEMENT OF SIGNIFICANCE

This well kept little shot-gun house is typical of the workingman's housing built in Bel Air in the last quarter of the 19th century. It was built on the eastern third of lot #5 in the Hays Addition. The land was part of the estate of merchant Thomas Hays, wealthy Harford County landowner.

This house is also an example of the difference between owneroccupied and rental housing. There is no need for an old house to be shabby. This is one of three tenant houses built by Stevenson Archer in 1885.

## 9 MAJOR BIBLIOGRAPHICAL REFERENCES

CONTINUE ON SEPARATE SHEET IF NECES	SARY
10 GEOGRAPHICAL DATA	
ACREAGE OF NOMINATED PROPERTY	
ASSERGE OF HOMINATED PROFESSION	
VERBAL BOUNDARY DESCRIPTION	
This property occupies parcel #122	9 in the Town of Bel Air
36' x 150'.	3 III
30 H 130 I	
LIST ALL STATES AND COUNTIES FOR PROPERTIES	OVERLAPPING STATE OR COUNTY BOUNDARIES
STATE	COUNTY
	COUNTY
STATE	COUNTY
11 FORM PREPARED BY	
NAME / TITLE	
Marilynn Larew, Architectural Hist	
ORGANIZATION	DATE
Town of Bel Air	838-8700
STREET & NUMBER	TELEPHONE
39 Hickory Avenue	STATE
	Maryland
Bel Air	rar yrana

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature, to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 Supplement.

The Survey and Inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

RETURN TO: Maryland Historical Trust


The Shaw House, 21 State Circle

Annapolis, Maryland 21401

(301) 267-1438

	The state of the s			
MARYLAND HISTORICAL TRUST	SURVEY NUMBER: UA 7402			
21 STATE CIRCLE	HA-1493			
SHAW HOUSE	NEGATIVE FILE NUMBER:			
ANNAPOLIS, MARYLAND 21401	TILE NUMBER:			
	UTM REFERENCES:			
HISTORIC SITES SURVEY FIELD SHEET				
Individual Structure Survey Form	Zone/Easting/Northing			
	II C C C C			
	U.S.G.S. QUAD. MAP:			
	DDDCDV			
	PRESENT FORMAL NAME:			
COUNTY: Layord	Guandler House			
TOWN: Bel an	ORIGINAL FORMAL NAME: Circher's Tenant House			
LOCATION: 133 Thomas	Tenant House			
195 mamor	TRESENT USE: Originate Aug. D.			
	JUNEOTHAL USE:/			
COMMON NAME;	ARCHITECT/ENGINEER:			
- Wandler House				
FUNCTIONAL TYPE: private residence	BUILDER/GONTRACTOR:			
OWNER: Mrs. Magil Chandler	I John F. Jensan			
ADDRESS: 133 Thomas	PHYSICAL CONDITTION OF CHRYS			
Belan, md.	Excellent (*) Good ( )			
ACCESSIBILITY TO PUBLIC:	Fair() Poor:()			
Voc	THEME: architecture			
LEVEL OF SIGNIFICANCE:	STYLE: Jernacular			
	DATE BUILT:			
Local() State () National() GENERAL DESCRIPTION:	Withwels 1886-1904 1885			
Structure I C	1704 1803			
Structural System				
1. Foundation: Stone()Brick()Concr 2. Wall Structure	ete()Concrete Plant()			
2. Wall Structure	( ) doncrete block( )			
A. Wood Frame: Post and Beam()B.	alloon()			
The state of the s	\			
C. Iron() D. Steel() E. Other	alloon( ) )Stone( )Concrete( )Concrete Block( )			
wall covering: Claphoard() Roard	- 1 p			
Novelty()Stucco()Sheet Metal	( )Aluminum( )Asphalt Shingle( )			
Brick Veneer()Stone Veneer()	( )Aldminum( )Asphalt Shingle( )			
Bonding Pattern				
4. Roof Structure	Other:			
A. Truss: Wood()Iron()Steel()C	· · · · · · · · · · · · · · · · · · ·			
5. Roof Covering: Slate()Wood Shingl Built Up()Rolled()Tile()Othe	/ )			
Built Up()Rolled()Tile()Othe	e( )Asphalt Shingle( DSheet Metal( ) -			
b. Engineering Structure.	r:			
/ Other·				
Appendages: Porches()Towers()Cupolas()Do: Wings ()Other:				
Wings ( )Other:	rmers()Chimneys()Sheds(WElls())			
Roof Style: Gable()Hip()Shed()Flat()Mans Saw Tooth()With Monitor()With Bellcast				
Saw Tooth()With Monitor()With Bellcast	sard()Gambrel()Jerkinhead()			
Other:	( )With Parapet( )With False Front( )			
Number of Stories: 2				
Number of Bays:				
Number of Bays: 2 x 2 plus sked (rug	Entrance Location: Thomas A			
7 mensions: 101/37/	) I would be seen that the see			
THREAT TO STRUCTURE:				
	OCAL ATTITUDES:			
Development(V) Deterioration()				
Alteration ( )Other:				
Alteration ()Other:	ixed() Other:			

A DE DE LOCALITE CONTRACTO CONTRACTO DE CONT	HA-1493
ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESC well kept wendows & so or posts plain balustrade cen- plain thin surrounds or 2 hour pane travsom Add ell (w) back - arphal	uall-shedouz-pack w chamfined tu cheming in Corbelled cap ug door whalf glass It
RELATED STRUCTURES: (Describe)	
1 congrage	
STATEMENT OF SIGNIFICANCE:	
STATEMENT OF SIGNIFICANCE: Working Man's housing b	int for Stevenson archer
REFERENCES:	
ii .	•
MAP: (Indicate North In Circle)	SURROUNDING ENVIRONMENT: Open Lane()Woodland()Scattered Buildings() Moderately Built Up()Densely Built Up() Residential()Commercial() Agricultural()Industrial() Roadside Strip Development() Other:
Tuomar Jag	M- Larent  RECORDED BY:  Town of Bellie  ORGANIZATION:  29 May 79  DATE RECORDED!



HA-1493 Chardler House, 133 Themas St Bolain



Chandle Lucke, 133 Thomas It, Bellin HA-1493 l. + 7 2/11